CS 315-01 Processor Design Hazard Unit Pipelining

4 types of modifications

Inverting the dock to the DegFile

so that WB can happen on FIRST half

of the clock cycle

CLK

WO DR Seduce to
two nops for
alate

2) Forwarding

3) LD Stalling

4) Control Hazard